



Print & Check

1. No matter what software you use to print, set your print scaling size to “100%” or “none scale” or “actual size”
2. After printing the layout, use your ruler to measure whether the 10cm or 5in line segment in the figure matches.

Print size confirmation



ZToughness

ztleather.co
ztoughness.gumroad.com
facebook.com/groups/ztoughness
youtube.com/@ztoughness

Tools & Materials

Leather Suggest

Thickness: 1.2mm

Type: Vegetable Tanned

Tools

Penknife

Cutting Knife

Utility Knife

Cutting Mat

Hammer

Leather Holes Punch(1mm, 3mm, 9mm)

Needle and Thread

Sandpaper

Leather Burnisher


Adhesive Eraser

3M Spray Mount


Treatment Agent

Leather Finish

Else Parts




Magnetic Bag Clasp 14mm



x1




Glove snap 10mm



x2



Double Cap Rivet “6x6” mm




x2

D-Ring



12mm

x2



Drawing Notation

- cut line
- • • • • punch hole position
- A1, A2... cutting piece number
- ✂ — ✂ trim lines for imposition
- 3 (N) mm hole (reference the size)
- skiving leather
- mask cut line

